

SOUTH PARK DESIGN REVIEW COMMITTEE March 25, 2019




DETAILED DESIGN CHANGES

- Several envelope revisions post-DRC approval in January 2016
- Changes made during detailed design phase for technical & operational reasons:
 - YMCA 3rd floor vision glass partially removed at east & north faces
 - Curve balcony railing revised
 - Pavilion & Curve roof lines revised



PAVILION NORTH ELEVATION – ORIGINAL


- Inset balcony provided outdoor space for YMCA third floor child care centre
- Glazing spans across ground floor





PAVILION NORTH ELEVATION - REVISED


- Balcony removed from YMCA third floor
 - Daycare not permitted, outdoor space no longer required
 - Studios designed in area
 - Glazing reduced to increase energy efficiency & reduce costs
- Glazing altered on natatorium façade to meet operational safety & security requirements





SOUTH PARK – GROUND FLOOR GLAZING

Areas in blue denote glazing at ground level





EAST ELEVATION – ORIGINAL


 Vision glass across third floor





EAST ELEVATION – REVISED

- Glazing altered on YMCA third floor
 - Detailed design requirement operationally for YMCA for studios & child care space





CURVE NORTH ELEVATION – ORIGINAL


 Pre-finished metal or ceramic panel at raised pool deck





CURVE NORTH ELEVATION – REVISED

Raised exterior amenity space shifted west to eliminate double railing condition & to expand usable amenity area





ROOF PROFILES – ORIGINAL

- Curved & canted roof profile
- Complicated profile due to angle of rampart view plane





ROOF PROFILES – REVISED

- Roof line redesigned for:
 - View plane conformance
 - Snow & ice management
 - Constructability

