
HALIFAX

Heritage Advisory Committee

Case No. H00484 2500 Creighton Street, Halifax Heritage Registration

Location






Application Details

- This is an application by the property owner, the St. Paul's Home Society, a registered nonprofit organization in Halifax.
- Morris House has been the subject of an 11 year conservation project involving several non-profit groups that saw the house moved to its current location from Morris Street in 2013, and subsequently rehabilitated with the aim of providing community uses on the site.






Age



Town of Halifax, 1777 (NSARM)



Morris House c.1840, by J.S. Clow (NSARM)

- Based on historical research into property title, and supported by dendrochronological (tree ring dating) analysis, the year of construction is estimated to be 1764;
- This would make Morris House the oldest wooden residence, and fifth-oldest structure in HRM.

 HALIFAX

Evaluation Criteria

1) Age

Date of Construction	Points	Timeline
1749 - 1785	25	Halifax Garrison Town to the Loyalist migration
1786 - 1830	20	Boom period following construction of Shubenacadie Canal
1831 - 1867	16	From Boom to Confederation
1868 - 1899	13	Confederation to the end of the 19 th century
1900 - 1917	9	Turn of the Century to Halifax Harbour Explosion
1918 - 1945	5	The War Years
1945 - Present	3	Post-War



Historical Importance

2a) Relationship to Important Occasions, Institutions, Personages or Groups



Charles Morris



Building relocation in 2013 (Huffington Post)

- Charles Morris I was the first Surveyor General of Nova Scotia and laid-out several significant towns, including Halifax in 1949. His son and grandson subsequently also held that title and ran their business from the Morris House.
- The building also received national media attention during its high-profile relocation in 2013.

 HALIFAX

Evaluation Criteria

2a) Relationship to Important Occasions, Institutions, Personages or Groups

Nationally	Points	Comments
Intimately Related	16 - 20	
Moderately Related	11 - 15	
Loosely Related	1 - 10	
Provincially	Points	Comments
Intimately Related	11 - 15	
Moderately Related	6 - 10	
Loosely Related	1 - 5	



Evaluation Criteria

3) Significance of Architect or Builder

Most modest structures during this period were built and designed by the property owner, or by local trades-people based on common designs and techniques. In this case there is no information available on the builder or architect.

3. Significance of Architect/Builder

Status	Points	Comments
Nationally	7 - 10	
Provincially Significant	4 - 6	
Locally Significant	1 - 3	
Not Significant	0	



Evaluation Criteria 4a) Construction Type

Morris House is one of only two surviving buildings in Halifax known to have been built with brick "nogging" between the structural timber framing. As a rare example of colonial building technology, a high score is recommended.



Brick "Nogging"

4. Architectural Merit

A) Construction type	Points	Comments
Very rare/ early example	7 - 10	
Moderately rare/ early	4 - 6	
Somewhat rare/ early example	1 - 3	
Not rare/ common example	0	



Architectural Merit

4b) Style

Morris House is a good and early example of colonial Georgian Architecture with it's simple form, truncated roof and Scottish dormer.

The character-defining elements of the Morris House include:

- truncated, pitched roof;
- wood shingle cladding;
- five-sided Scottish dormer;
- c.1890 front bay widows;
- c.1890 enclosed front porch;
- wooden hung, sash windows with divided lights;
- cornerboards and returns; and
- dentils under eave.



Morris House in Spring 2020



Building Evaluation Criteria

4. Architectural Merit

B) Style	Points	Comments
Very rare/ early example	7 - 10	
Moderately rare/ early	4 - 6	
Somewhat rare/ early example	1 - 3	
Not rare/ common example	0	



Architectural Integrity







1840 1953 2020



Changes include:

- Removal of central gable dormer;
- Addition of Victorian elements on front;
- Rear addition added in 2017.



Building Evaluation Criteria

5. Architectural Integrity

Architecture	Consider any additions/ removal/ alterations to windows, doors, porches, dormers, roof lines, foundations, chimneys, and cladding.		
Exterior	Points	Comments	
Largely unchanged	11 - 15		
Modest changes	6 - 10		
Major changes	1 - 5		
Seriously compromised	0		



Relationship to Surrounding Area





Morris house has been relocated to a residential neighbourhood of two and three storey buildings, many with similar architectural features.



Building Evaluation Criteria

6. Relationship to Surrounding Area

Points	Comments
6 - 10	The building is an important architectural asset contributing to the heritage character of the surrounding area.
1 - 5	The Architecture is compatible with the surrounding area and maintains its heritage character.
0	Does not contribute to the character of the surrounding area.



Recommendation

It is recommended that the Heritage Advisory Committee recommend that Regional Council:

- Set a date for a heritage hearing to consider the inclusion of 2500 Creighton Street, Halifax, as shown on Map 1, in the Registry of Heritage Property for the Halifax Regional Municipality; and
- 2. Approve the request to include 2500 Creighton Street, Halifax, as shown on Map 1, in the Registry of Heritage Property for the Halifax Regional Municipality as a municipal heritage property.

