

P.O. Box 1749 Halifax, Nova Scotia B3J 3A5 Canada

Item No. 12.2.1
Appeals Standing Committee
April 12, 2018

**TO:** Chair and Members of Appeals Standing Committee

-Original Signed-

SUBMITTED BY:

Steve Higgins, Acting Director, Planning & Development

**DATE:** March 20, 2018

SUBJECT: Demolition Report – Case #305184, 209 Scotts Point Road, East Dover

#### <u>ORIGIN</u>

Staff, pursuant to the Halifax Regional Municipality Charter (the "Charter").

#### LEGISLATIVE AUTHORITY

Sections 355, 356 and 3(q) of the Halifax Regional Municipality Charter, S.N.S., 2008 C.39.

## **RECOMMENDATION**

It is recommended that the Committee pass the following resolution:

The Committee finds the property to be dangerous or unsightly as per section 3(q) of the Charter and as per section 356 of the Charter, **orders demolition** of the accessory structure, including but not limited to, the removal of all demolition debris, backfilling of any foundation or crawl space, and disconnecting any and all utility connections to the standard set by each respective utility service provider, so as to leave the property in a neat, tidy, environmentally compliant and safe condition within thirty (30) days after the Order is posted in a conspicuous place upon the property or personally served upon the owner. Otherwise, the Municipality will exercise its rights as set forth under Part XV (15) of the Charter.

## **BACKGROUND:**

There have been four previous dangerous or unsightly cases at the property. The cases were all closed as owner compliance.

This case is a result of a service request received on January 8, 2018. The complainant advised of a deteriorated and unsafe building and wharf where the debris is falling into the water and affecting the watercourse.

The Compliance Officer attended the property on January 8, 2018 and noted derelict vehicles, debris, scattered wood, large wooden wharf pilings at the shore and multiple deteriorated accessory structures.

The Compliance Officer is addressing the derelict vehicles under case # 305273. An Order to Remedy was issued on February 16, 2018. The Compliance Officer reinspected the property on March 9, 2018 and the case was closed as owner compliance.

The Compliance Officer is bringing this case forward to the committee to request a Demolition Order for the deteriorated accessory structure (fishing building) located at 209 Scotts Point Road, East Dover.

#### **CHRONOLOGY OF CASE ACTIVITES:**

- 9-Jan-2018 The Compliance Officer conducted a site inspection at 209 Scotts Point Road, East Dover, hereinafter referred to as "the Property" (attached as Appendix B) and noted multiple derelict vehicles and parts throughout the property, scattered wood, and large wooden wharf pilings at the shore. There were multiple deteriorated accessory buildings. This report will focus on the large deteriorated wooden accessory structure suspended over the water with a collapsed roof, collapsing foundation beams and a massive hole in the side of the building.
- 10-Jan-2018 The property owner was at the property when the Compliance Officer conducted the site inspection. The Compliance Officer stated that the accessory structure (fishing building) needed to be repaired or demolished. The Compliance Officer hand delivered a Notice of Violation (attached as Appendix C) to the property owner.

The property owner and her brother advised that the work would be weather and tide dependent as the building is situated on the coastline.

- 11-Feb-2018 The Compliance Officer conducted a site inspection and noted no change to the condition of the property. The Compliance Officer spoke with the property owner's brother and advised him he would be issuing an Order to Remedy for the derelict vehicles and debris and that the accessory structure needed to be repaired or demolished.
- 16-Feb-2018 The Compliance Officer conducted a site inspection and noted no change to the condition of the property. The Compliance Officer spoke with the property owner's brother and advised him that HRM would be requesting a Demolition Order for the accessory structure through the Appeals Standing Committee. The property owner's brother advised the Compliance Officer he intends to have the structure designated as a heritage building.
- 21-Feb-2018 The Building Official submitted a structural integrity report for the building (attached as Appendix D).

The overall comments regarding the structure are: "Building is not secured from the public and the potential for further collapse exists under heavy wind, snow or surf

conditions. Building is not safe and would require an extensive renovation to conform to current building codes." 02-Mar-2018 The Compliance Officer was contacted by the complainant who requested an update on the case and when the property would be brought into compliance. 23-Mar-2018 The Compliance Officer posted a Notice to Appear (attached as Appendix E) at the property. A copy of the Notice was also sent via registered mail.

## FINANCIAL IMPLICATIONS

There are no financial implications if the owner complies with the Order. If the Municipality is required to complete the work, the costs will form a debt against the property which may be collected in the same manner as taxes pursuant to the Halifax Regional Municipality Charter, S.N.S., 2008, C.39.

## **ALTERNATIVES**

The state of the property suggests no viable alternative to the recommendation by Staff.

## **RISK CONSIDERATIONS**

The risk consideration rates moderate. The building presents an allurement and due to the advanced state of deterioration, the building poses a safety risk to individuals if they were to enter.

## **ENVIRONMENTAL IMPLICATIONS**

Avoids unsafe living conditions which aligns with Sustainability Principle #4 of the Corporate Sustainability Filter.

## **ATTACHMENTS**

Appendix A:	Copy of the Legislative Authority – Halifax Regional Municipality Charter
Appendix B:	Copy of the Nova Scotia Property Records Map
Appendix C:	Copy of the Notice of Violation dated January 10, 2018
Appendix D:	Copy of the Building Official's Report dated February 21, 2018

Appendix E: Copy of the Notice to Appear dated March 23, 2018

A copy of this report can be obtained online at Halifax.ca or by contacting the Office of the Municipal Clerk at 902-490-4210.

Report Prepared For: Kory O'Neill, Compliance Officer II, By-law Standards, 902.293.1406

-Original Signed-

Report Approved By:

Penny J. Henneberry, Manager, Buildings and Compliance, 902.579.0250

## **APPENDIX A**

## Halifax Regional Municipality Charter ("HRM Charter) Subsection 355, 356 and 3(q)

HRM Charter, subsection 355 (1) (2) as follows:

- 355 (1) The Council may, by policy, delegate some or all of its authority pursuant to this Part, except the authority to order demolition, to the Administrator.
  - (2) The Council may, by policy, delegate its authority pursuant to this Part, or such of its authority as is not delegated to the Administrator, to a community council or to a standing committee, for all or part of the Municipality.

HRM Charter, subsections 356(1)(3), as follows:

- 356 (1) Where a property is dangerous or unsightly, the Council may order the owner to remedy the condition by removal, demolition or repair, specifying in the order what is required to be done.
  - (3) Where it is proposed to order demolition, before the order is made not less than seven days notice must be given to the owner specifying the date, time and place of the meeting at which the order will be considered and that the owner will be given the opportunity to appear and be heard before any order is made.


## HRM Charter, subsection 3(q) as follows:

- (q) "dangerous or unsightly" means partly demolished, decayed, deteriorated or in a state of disrepair so as to be dangerous, unsightly or unhealthy, and includes property containing
- (i) ashes, junk, cleanings of yards or other rubbish or refuse or a derelict vehicle, vessel, item of equipment or machinery, or bodies of these or parts thereof,
- (ii) an accumulation of wood shavings, paper, sawdust, dry and inflammable grass or weeds or other combustible material,
- (iia) an accumulation or collection of materials or refuse that is stockpiled, hidden or stored away and is dangerous, unsightly, unhealthy or offensive to a person, or
- (iii) any other thing that is dangerous, unsightly, unhealthy
- or offensive to a person, and includes property or a building or structure with or without structural deficiencies
- (iv) that is in a ruinous or dilapidated condition,
- (v) the condition of which seriously depreciates the value of land or buildings in the vicinity,
- (vi) that is in such a state of non-repair as to be no longer suitable for human habitation or business purposes,
- (vii) that is an allurement to children who may play there to their danger,
- (viii) constituting a hazard to the health or safety of the public,
- (ix) that is unsightly in relation to neighbouring properties because the exterior finish of the building or structure or the landscaping is not maintained,
- (x) that is a fire hazard to itself or to surrounding lands or buildings,
- (xi) that has been excavated or had fill placed on it in a manner that results in a hazard, or
- (xii) that is in a poor state of hygiene or cleanliness;

## **APPENDIX B**



## **Property Online Map**



PID: 40065732 Owner: PHYLLIS MARIE ZINCK AAN: 05051266

Address: 209 SCOTTS POINT Value: \$174,900 (2018 RESIDENTIAL County: HALIFAX COUNTY

ROAD TAXABLE) LR Status: LAND REGISTRATION

EAST DOVER

The Provincial mapping is a graphical representation of property boundaries which approximate the size, configuration and location of parcels. Care has been taken to ensure the best possible quality, however, this map is not a land survey and is not intended to be used for legal descriptions or to calculate exact dimensions or area. The Provincial mapping is not conclusive as to the location, boundaries or extent of a parcel [Land Registration Act subsection 21(2)]. THIS IS NOT AN OFFICIAL RECORD.

## Property Online version 2.0

This page and all contents are copyright @ 1999-2003, Government of Nova Scotia, all rights reserved.

# HALIFAX

# Municipal Compliance

## Notice of Violation Notice Served Upon: Name or address This is to advise that you are in violation of the following municipal and/or provincial legislation: HRM By-law A-300 Animals HRM By-law S-300 Streets HRM By-law C-300 Civic Addressing HRM By-law S-600 Solid Waste HRM By-law C-501 Vending HRM By-law S-801 Temporary Signs HRM Charter, Part XV Respecting HRM By-law S-1000 Sidewalk Cafes Dangerous or Unsightly Premises HRM By-law T-1000 Taxi & Limousine HRM By-law N-300 Nuisances Details of violation(s): Violation(s) to be rectified as per the following: Notice of Re-inspection: A re-inspection will be performed on to confirm the above noted violations have been rectified. If you have any queries regarding this matter, please contact the issuing Officer prior to the re-inspection date. Issuing Officer Date (dd/mm/yy) Issuing Officer Phone Number Time (hh/mm) ORIGINAL SIGNED Issuing Officer Signature Case Number

For information on municipal legislation visit the Halifax Website at www.halifax.ca/legislation or call the Citizen Contact Centre at 311. If calling outside the HRM but within NS call 1-800-835-6428 toll free.

## **APPENDIX D**

# HALIFAX

## Building Official's Report

Planning and Development PO Box 1749 Halifax, NS 83J 3AS

Pursuant to Part XV of the Halifax Regional Municipality Charter
As requested by the By-Law Compliance Officer, an inspection of the property located at:

Property Address	PID	Inspection Date
209 Scotts Point Rd, East Dover	40065732	Feb 21/18

Building Feature	Condition Relative to Habitability and Structural Integrity	
Main Structure	Building is a wood framed accessory building approximately 16'x16'. Cladding is wood and asphalt shingles. Areas of the cladding and sheathing are missing, leaving some wall studs exposed. The bottom of the exterior wall at the left side of the building has collapsed and the exterior wall is sagging.	
Foundation	<ul> <li>Supported by wooden posts bearing on large rocks on the shore.</li> <li>Wooden support post has partially collapsed at left side of building.</li> </ul>	
Heating Appliances	Unable to confirm.	
Chimney	Metal, prefabricated     Extremely rusty, no cap	
Roof	Asphalt roof shingles     There is a significant sag at the ridge.	
Building Services	No power to the building.     Unable to confirm connection of other services.	

## Public Safety Considerations

- · Building is not secured from the public.
- The potential for further collapse exists under heavy wind, snow or surf conditions

## Comments Regarding Repair or Demolition

Building is not safe and would require an extensive renovation to conform to current building codes.

-Original Signed-	ORIGINAL SIGNED	ORIGINAL SIGNED
Building Official (please print)	Signature	Supervisor's Initials

Form on 201

## **APPENDIX E**



IN THE MATTER OF: Section 356 of the Halifax Regional Municipality Charter, S.N.S., 2008, C.39
Hereinafter referred to as the "Charter"

-and-

IN THE MATTER OF:

209 Scotts Point Road, East Dover; Nova Scotia;

Hereinafter referred to as the "Property"

-and-

IN THE MATTER OF:

Deteriorated and decayed structure

Hereinafter referred to as the "Building"

TO:

Phyllis Marie Zinck

WHEREAS you are the owner of the Property:

AND WHEREAS situated on the Property is the Building identified as dangerous or unsightly as per section 3(q) of the Charter;

TAKE NOTICE that you are hereby requested to appear before the Appeals Standing Committee ("Committee") at 10:00am on April 12, 2018 in the Council Chambers, 3rd Floor, City Hall, 1841 Argyle Street, Halifax, Nova Scotia;

At which time the Committee will consider the following application:

APPLICATION by Staff for an Order pursuant to section 356 of the Charter, to require demolition of the Building, removal of all demolition debris, backfilling of any basement or crawl space and the disconnection of any and all utility connections to the standard set by the service provider within thirty (30) days of the date of the Order.

SECTION 356(3) OF THE CHARTER provides the opportunity for the owner of the Property to appear and be heard by the Committee;

DATED at Halifax, Nova Scotia this 23rd of March, 2018

**ORIGINAL SIGNED** 

Kory O'Neill Compliance Officer 902-293-1406 Scatt Hill Administrator Halifax Regional Municipality